

# Car Inspectors

## Technician's Inspection/Road Test list:

System	Condition (okay if checked):	Description of problem :
DMV History		
VIN #		
Title		
Accidents		
Salvage Title		
Smog legal		
Body/Frame:		Dr dr hard to close.Unfnshd bndo various areas. (C-Photos)
Glass		Pass door glass infrs w/driprail.
Paint		Chipping in various places. Finish poor due to poor bodywork.
Trim		Wtherstrippg @ wndws poor fit. Discolored, scratched, bent
Rust		Lwr fender areas/rcker pnls. Rear trunk area @ spker deck
Accidents		R/F. Right side.
Previous Repairs		R/F, Trunk deck area, RR quarter, c-photos
Frame		Repaired/ pulled @ R/F.
Exhaust system		Aftermarker exhaust exits under car
Transmission/ Drivetrain		Trans over filled
Worn Parts	√	
Leaks		Speedometer drive
Wheels/Tires		Rear trs worn out. LF 6/32, R/F 6/32 (outsde shoulder worn).
Suspension/steering	√	
Brake hydraulics	√	
ENGINE CMPRTMNT:		Rusted, loose components. Heater cover loose, dmgd
Engine:		Vac advance disconnected
Oil condition		Dirty
Noises		Excess valvetrain noise. Alternator "roars"
Leaks	√	
Idle quality		Fast, rough idle.
Compression check	√	
Steering hydraulics		Reservoir cap loose.
Starting/charging		Battery low. Alt overcharges @ 17.6 volts.
Radiator/cooling system		Htr core dmgd/ missing . Fan shroud mssng
Antifreeze	√	
Leaks		Upper radiator tank.
Corrosion	√	
Belts/hoses	√	
Transmission Fluid		Overfilled.
A/C system:	N/A	
Noises		
Leaks		
Interior:	√	
Upholstery	√	
Controls/features		Htr contrl console loose, controls sticking/ inop.
Dashboard		Lamp switch worn.